

友達光電贈與之間隙量測(Cell Gap)機 軟硬體簡易使用說明

作者：逢甲大學自動控制系 鄭智聰 gene70288@hotmail.com

指導：大塚科技 陳映任 <sean_chen@photal.com.tw>

逢甲大學自動控制系 林宸生 lincs@fcu.edu.tw

友達光電 AUO 吳泰德 taite.wu@auo.com

機台：大塚科技 RETS-3000



一、硬體使用簡易說明：

1. 使用電壓 110v
2. 將插頭插入 110v 插座後，圖 1 之 INPUT1 即亮燈表示已接上電源。
3. 將圖 2 之開關扳成 ON 後，INPUT2 即亮燈表示電源已送入降壓器待機中。
4. 按下圖 1 之 ON 鈕後，亮燈並開啓量測機、電腦及相關裝置之電源，進入啓用狀態。



圖 1 電源輸入顯示說明



圖 2 電源開關之一

二、軟體使用說明：

1. 啓動 RETS-QC software，即顯示圖 3 之介面
介面說明：

- 1.1 Calibration (F1)：進行機台之校準動作。
- 1.2 Inspection (F2)：檢查(自動量測)。
- 1.3 Manu.meas (F3)：手動量測。
- 1.4 Recipe edit (F4)：編輯配方。
- 1.5 3-D display (F6)：3-D 顯示。
- 1.6 End (F9)：End。




圖 3 RETS-QC software 介面

2. Calibration 之介面，如圖 4

介面說明：

- 2.1 可顯示 analyzer/polarizer 之校正況台。
- 2.2 可顯示目前對正之座標、空氣座標、樣本的座標
- 2.3 Meas.start (F1)：開始量測。
- 2.4 Cond.Edit (F2)：編輯狀態。
- 2.5 Ref.history (F3)：查詢過去的量測結果





圖 4 Calibration 之介面

3. 校正完畢之確認畫面，如圖 5



4. 校正完畢並產生結果，如圖 6




圖 6 校正結果顯示

藍色線為 polarizer 旋轉角度 45 度
綠色線為 analyzer 旋轉角度 135 度

Wlength (nm)	400.0	450.0	500.0	550.0	600.0	650.0	700.0	750.0
Ref. Re	635.12	621.90	612.80	606.10	601.00	597.10	593.90	591.40
Meas. Re	630.62	619.85	612.14	606.44	602.11	598.73	596.05	593.89

圖 7 校正結果

Wlength

Ref.Re 參考結果

Meas.Re 校正結果

5. Manu.meas 手動量測介面，如圖 8




圖 8 手動量測介面

6. 單點 GAP 測量結果，如圖 9

可量測之結果有：

1. Gap.V sample GAP 數值
2. Re.R
3. Re.V




圖 9 單點 GAP 值

7. 多點 sample 之量測數值，如圖 10

由 Statist.Res 統計結果 可顯示出

1. Max. 最大 GAP 值
2. Min. 最小 GAP 值
3. Range 最大與最小 GAP 值之範圍
4. Aver. 平均 GAP 值
5. Std. Devi. 標準差(standard deviation)
6. Uniform 樣本平均值
7. CV% 變異係數(coefficient of variation) 標準差除以平均值所得之百分比%

Re-R

$$450/600 : 475.37 / 428.08 = 1.110$$

$$600/750 : 428.08 / 406.19 = 1.054$$

Re-V




圖 10 多點 GAP 值

$$459.21 / 440.19 = 1.04320861$$

$$440.19 / 431.38 = 1.020$$

8. 編輯配方

Cell gap inspection software - Recipe editing

Group name Recipe No.

Samp. Cond. Eval. crit. cond. Sys. Cond. Meas. point

Reci. name

Rear rubbing a. °

Twist a. °

dn wavelength nm

dn (25°C) A

aGap+b correct a b

Cal. order Cal. Mode

Wlength cal.range ~

Eval.crit.(Re.ratio) 450/600 ~

600/750 ~

dn. kT. dn wlength
Select reg. va.

Operator ID a2323 Lamp use time 4h Temp. --.°C

Cell gap inspection software - Recipe editing

Group name Recipe No.

Samp. Cond. **Eval. crit. cond.** Sys. Cond. Meas. point

Range eval.

Every point Average

Eval. crit. (Min.) um

Eval. crit. (Max.) um

Vary eval.

SD SD (3) Range

Eval. crit.(deviat.)

Reci. Print (F4)

Close (F9)

Operator ID a2323 Lamp use time 4h Temp. ...°C

Cell gap inspection software - Recipe editing

Group name Recipe No.

Samp. Cond. Eval. crit. cond. **Sys. Cond.** Meas. point

Gate time **Normal** msec
 Cross meas. msec

Accum. times Count
 Smoothing Point
 Diffe. point Point
 Noise cut Sig
 Amp. gain **Normal** ▾
 Disp. X scale ~
 Disp. Y scale ~
 Y scale auto

Lamp gain L H

Operator ID a2323 Lamp use time 4h Temp. --.°C

Cell gap inspection software - Recipe editing

Group name Recipe No.

Samp. Cond. Eval. crit. cond. Sys. Cond. Meas. point

Sample size (,)

Origin of sample

Manu. meas. Point

Meas. point

	Coordi. X	Coordi. Y
1	0.00	0.00
2	216.00	83.00
3		
4		
5		
6		

Drive Test

Matrix select

5-point select

Line select

Optional select

Sample center (,)

Edit drive

Reci. Print (F4)

Close (F9)

Operator ID a2323 Lamp use time 4h Temp. --.°C

